

Trouble-shooting for ink firmness

Q: Why is my paint stripped of plexiglass or aluminum

A: The plexiglass or aluminum materials are special (smooth surface or special processed). To increase ink firmness, suggest use coating before print.

---Choose coating for different materials.

There are different coating to print with plexiglass, metal, acrylic etc.

---Coating usage.

Wipe coating evenly on the material surface and wait 3-5 mins after coating can dry completely.

Notice: if material surface is special processed before, the ink can not stay well even with coating.